




RECOMMANDATION : Il est préconisé de remplacer simultanément le relais Y et le condensateur X
RECOMMENDATION: It's recommended to replace simultaneously both relay Y and capacitor X

Index PDF	Référence	Designation commerciale	Tarif
A	39919	ZÓCALO 230/50/1 J80U SPV	54.50 EUR
B	39888	CABLE DE ALIMENTACION	15.50 EUR
M	39926	CONJ MOT 230/50 J80U SPV	419.10 EUR
P	39585	[Spare parts translation not found]	55.70 EUR
X	600018S	CONDENSADOR 60µF 250V	16.60 EUR
Y1	500289S	RELÉ MTRPH 46-39	17.70 EUR
1	39895	SOP. MOT. J80U SPV	386.00 EUR
2	39896	PALANCA BLOQUEO J80U SPV	38.80 EUR
3	39897	CENTRADO CUBA J80U SPV	10.70 EUR
4	501010S	ANILLO ESTANQU. 15X35X6	10.10 EUR
5	39898	CUBIERTA COJINETE J80U	5.60 EUR
6	39899	BLOQUE ENC/APAG J80U SPV	7.60 EUR
7	39900	COJINETE IZQ. J80 SPV	19.30 EUR
8	507007S	MICRORRUPTOR V15T16-CZ100	8.00 EUR
9	39901	COJINETE DER. J80U SPV	16.30 EUR
10	39902	DEFLECTOR EJE J80U SPV	6.00 EUR
11	39903	CENTRADO MOTOR J80U SPV	9.10 EUR
12	49155	[Spare parts translation not found]	5.80 EUR
13	39905	RODS 6002-2RS+6201-2RS SA	25.00 EUR
14	39906	TUBO DE VENTIL. J80U SPV	19.20 EUR
15	118512S	[Spare parts translation not found]	5.40 EUR
16	39907	DEFLECT. MOTOR J80U SPV	8.10 EUR
17	39927	PANEL MANDO J80U SPV	7.60 EUR
18	39283	[Spare parts translation not found]	22.10 EUR
19	39909	TAPA J80U SPV	59.40 EUR
20	39910	CESTA J80U SPV	112.20 EUR

21	39911	DISCO RALLADOR J80U SPV	32.90 EUR
22	39929	ARANDELA INCL. J80U SPV	6.30 EUR
23	39912	FILTRO J80U SPV	61.60 EUR
24	39913	BUJE J80U SPV	17.90 EUR
25	39914	COLLARÍN CUBA J80U SPV	11.70 EUR
26	39915	CUBA J80U SPV	79.60 EUR
27	39916	PICO VERTEDOR J80U SPV	5.10 EUR
28	39917	COLECTOR PULPA J80U SPV	21.30 EUR
29	39928	PIES (X4)	6.60 EUR
30	39960	CONJ TORNILLO J80 ULTRA	7.40 EUR
31	39516	ANTIGOTEO J100U SPV	19.10 EUR
32	49180	[Spare parts translation not found]	31.50 EUR
33	39986	[Spare parts translation not found]	36.00 EUR
34	49158	[Spare parts translation not found]	7.10 EUR
35	49226	[Spare parts translation not found]	Contactarnos
36	49227	[Spare parts translation not found]	Contactarnos
37	49228	[Spare parts translation not found]	Contactarnos
38	49229	[Spare parts translation not found]	Contactarnos
39	49230	[Spare parts translation not found]	225.00 EUR